

# FIRE !!!!!

## Safety of your guests is most important!!!



BEFORE.....



AFTER.....



BEFORE.....



AFTER.....

The four photos above is telling the Fiber Palm story.

The story summed up in a couple of short sentences is :

- **Before:** Life expectancy 5-10 years.  
**After:** Life expectancy 50 years plus!!!!
- **Before:** Warranty zero  
**After:** Warranty 20 years
- **Before:** Longevity:- Material rotten 3-5 years.  
**After:** Longevity:- The second photo taken more than 10 years after changing.
- **Before:** Drastic colour changes.  
**After:** No colour change, no fading.
- **Before:** Insect infestation, allergies, bird damage, damage by monkeys, baboons etc.  
**After:** None of the above is any problem whatsoever.
- **Before:** Maintenance budget astronomically with netting needed to keep thatch down.  
**After:** No maintenance. No netting required.

## NB!! But what the photos do not show is that Fiber Palm Thatch has a UL94 Class B Fire rating.

The Gili Lankanfushi Resort catastrophe were burning sparks and embers carried by a strong eastern wind to adjacent chalets caused 7 chalets to and the main restaurant burn to ashes.

This would never have happened if the roofs were done with **Fiber Palm Thatch!!!**

**Sparklets carried by the wind will not ignite a Fiber Palm Synthetic roof**

See Below and let this never happen to your resort.

Also see, <https://www.youtube.com/watch?v=iPMgFD5ypQ8>



*The heroes were the Gili Lankanfushi Resort management and staff that not only saved the lives of their guests but also many of their personal belongings.*